



United States Steel  
Clairton Works  
400 State Street  
Clairton, PA 15025-1855

AFS 42-003-00032  
APCI 0  
ATPI 00 - Terminates Outage  
DTA 020305

March 5, 2002

Dr. Roger C. Westman  
Department of Air Quality  
Bureau of Air Pollution Control  
301 Thirty-Ninth Street  
Pittsburgh, PA 15201

U.S. Environmental Protection Agency  
Region III  
Air, Radiation & Toxics Division  
1650 Arch Street  
Philadelphia, PA 19103-2029  
ATTN: James W. Hagedorn (3AT23)

Assistant Council  
Department of Environmental Protection  
Southwest Region  
400 Waterfront Drive  
Pittsburgh, PA 15222-4745  
ATTN: Ward Kelsey, Esq.

Department of Justice  
Environmental and Natural Resource Division  
Environmental Enforcement Section  
P.O. Box 7611  
Ben Franklin Station  
Washington, D.C. 20044  
ATTN: David Street, Esq.

Subject: USS Reference Number: 02-0008  
Sulfur Plant Incinerator and Incinerator Stack  
USS Clairton Works

Gentlemen:

The attached form terminates the planned outage. Any questions concerning this matter should be referred to Coleen M. Davis at 233-1015.

Sincerely,

R. R. Terza  
General Manager  
Clairton Works Raw Materials

United States Steel LLC  
A subsidiary of USX Corporation

RECEIVED  
March 12, 2002  
Air Protection Division (3AP12)

ED\_002508A\_00000916-00001

NOTICE OF PLANNED OUTAGE OF EQUIPMENT  
ARTICLE XXI - SECTION 2108.1

1. Planned Outage Number: 02-0008 Termination
2. Date & Time of Breakdown: Date: 01/29/02 Time: 0920 hours
3. Company Name: USX Corporation - USS Clairton Works
4. Specific Equipment Involved or Affected: Sulfur Plant Incinerator and Incinerator Stack
5. BAPC Permit Number (if applicable):
6. Location: Clairton, PA
7. Nature and cause of breakdown: The spare sulfur plant incinerator stack (S-685A) and incinerator (B-684A) will be unavailable for service for approximately 2 weeks to clean the piping from the Claus Plant to the incinerator stack.
8. Identification of Emissions:
  - A. Type(s) (CO, NOX, SO<sub>2</sub>, Particulates, Hydrocarbons, etc.)  
The spare incinerator stack and incinerator will carry the load. No environmental impact is expected.
  - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). SO<sub>2</sub> is an eye, nose, and throat irritant.
  - C. Amount of each type emitted (or likely to be emitted).  
No environmental impact.
9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).  
The spare incinerator and stack carried the load.
10. Facility back in operation - Date: 03/01/02 Time: 0630 hours

Signature Coleen M. Davis Date 3/6/02  
Coleen M. Davis  
Environmental Control Engineer Phone: 233-1015